




THIS DRAWING IS FOR THE
PURPOSE OF OBTAINING
PLANNING PERMISSION ONLY

HOUSING SCHEDULE				
830 2/GJ/4/6/13				
PLOT	UNITS	BEDS	AREA	TOTAL SQ.M.
1, 13	2	3	81.02	162.04
2, 3, 9, 10, 11, 12, 14, 15, 27	9	2	67.02	603.18
4, 6	2	2	67.08	134.16
5	1	3	80.82	80.82
7	1	4	99.2	99.2
8, 21	2	3	101.36	202.72
16	1	2	69.83	69.83
17	1	2	67.74	67.74
18, 19, 20	3	3	87.95	263.85
22	1	3	85.95	85.95
23, 25	2	2	67.53	135.06
24	1	3	83.97	83.97
26	1	3	81.03	81.03
28, 29	2	3	86.64	173.28
30	1	2	73.32	73.32
TOTAL	30			2316.15



Reproduced from Ordnance Survey Map with the permission
of the controller of HM Stationery Office.
Crown Copyright reserved
Robert Doughty Consultancy Licence No. 100010613

CDM NOTE:

The design has been undertaken as far as possible to avoid risks to health and safety or to reduce and control the effects of any unavoidable risks.

All relevant information identifying the unavoidable risks has been passed to the planning supervisor for inclusion in the Health & Safety plan.

The Health & Safety plan will be issued by the planning supervisor with these drawings.

E	JB	Highways amends	29-10-13
D	JB	Footprints & roads amended visitor parking added	11-6-13
C	JB	Amended parking allocation	5-6-13
B	CJ	Amended footprints	4-6-13
A	GJ	Amended Parking / access	14-5-13

Rev.	By	Notes	Date

rdc
Robert Doughty
Consultancy

32 High Street, Helpingham
Sleaford, Lincolnshire NG34 0RA
Tel: 01529 421646
Fax: 01529 421358
Email: admin@rdc-landplan.co.uk
Web: www.rdc-landplan.co.uk

Client:
Rose Homes (EA) Ltd

Project:
Windmill Street, Whittlesey

Drawing title:
Proposed Site Layout

Drawing No. 830 - 2 - SL 201	Rev. E	Drawn GJ
---------------------------------	-----------	-------------

Scale 1:200@A1	Date 2-05-2013	Checked LMS/RJCD
-------------------	-------------------	---------------------

P:\Projects\830-899\830 Rose Homes\830-2 Redesign of Existing Housing Scheme, Windmill Street, Whittlesey\CAD Files\00-RDC Drawings\Current\Design Sheets.dwg, 30/10/2013 17:31:42

DO NOT SCALE from this drawing. All measurements should be checked against on site conditions and any discrepancies should be brought to the attention of the Robert Doughty Consultancy.